


PLATO

Plato® Tips to fit Pace® Air-Vac® and A.P.E. Desoldering Irons

Pace®	Plato®	L	D1	D2
Plato® Tips to fit Pace® SX-20, SX-25, SX-25V, SX-30, SX-30V SODR-X-TRACTORS®				
1121-0213	20-0109	1.00" (25.4)	.025" (0.6)	.060" (1.5)
1121-0480	20-0114	1.00" (25.4)	.030" (0.8)	.060" (1.5)
---	20-0815	1.00" (25.4)	.036" (0.9)	.065" (1.7)
1121-0479	20-0110	1.00" (25.4)	.040" (1.0)	.080" (2.0)
1121-0216	20-0113	1.00" (25.4)	.050" (1.3)	.090" (2.3)
1121-0217	20-0111	1.00" (25.4)	.060" (1.5)	.100" (2.5)
1121-0091	20-0112	1.00" (25.4)	.090" (2.3)	.125" (3.2)
Plato® Tips to fit Pace® SX-40A, SX-55A, SX-65A, SX-70 SODR-TRACTORS® with Plato® Adapter 33-0001				
1121-0485	20-025	1.75" (44.5)	.030" (0.8)	.080" (2.0)
1121-0486	20-040	1.75" (44.5)	.040" (1.0)	.080" (2.0)
---	20-050	1.75" (44.5)	.050" (1.3)	.090" (2.3)
1121-0255	20-060	1.75" (44.5)	.060" (1.5)	.100" (2.5)
Plato® Tips to fit Pace® SX-40A, SX-55A, SX-65A, SX-70 SODR-X-TRACTORS® with Plato® Adapter 33-001				
1121-0261	20-0030	1.75" (44.5)	.030" (0.8)	.080" (2.0)

Plato® Tip



Premium Quality for long life

Made of oxygen-free high-conductivity copper, protected inside and outside to minimize erosion by solder.

Tip Samples are available. Custom tip designs on request. () = mm

See [Desoldering Tip Cross Reference](#) for competitive cross reference to Air-Vac® and A.P.E.®

Packaged 10 pieces per pack

