

TW-DIY-5110



zoom photo

PARTS LIST - KIT 110

Resistors (0.25W carbon, 5%)

1K2 brown red	R8.....	1
1K5 brown green	R1.....	1
2K7 red violet	R4.....	1
39K orange white orange.....	R9,10.....	2
47K yellow violet range.....	R5.....	1
100K brown black yellow.....	R6,7.....	2
270K red violet yellow	R3.....	1
2M2 red red green	R2.....	1

Capacitors

1.8nF polyester	C2	1
4.7nF polyester	C3	1
47nF polyester	C1	1
10uF 16/25V electrolytic	C4,5	2

Semiconductors

LM324, Quad Op-Amp.....	IC1.....	1
1N4148 diode	D1.....	1

Miscellaneous

Slide switch.....	SW1,2.....	2
Piezo external drive buzzer.....		1
9V battery harness		1

PCB,

K110.....		1
-----------	--	---