
 [Search This Product Catalogue](#)

[Product Catalogue for Static Control Products for EPAs](#) > [3M™ Static Control Products for EPAs \(Electrostatic Protected Area\)](#) > [4. 3M™ Continuous Monitors](#) > [1. 3M™ Workstation Monitor](#) > [3M™ 3057 Monitor Stand-By Jack](#) >

 [Printer-friendly format](#) **3M™ 3057 Monitor Stand-By Jack**



The 3M™ 3057 Monitor Stand-by Jack allows an operator to disconnect a ground cord from the wrist band and leave the workstation without deactivating the 724 Workstation Monitor.

[\[click to enlarge\]](#)

**Additional Information**

When personnel leaves the workstation they simply detach the cord from the wrist band and plug it into the 3M™ 3057 Stand-By Jack. When the jack is grounded, the green light will illuminate and the yellow "Caution" lamp will slowly flash .

- ▼ **Electronics Manufacturing**
  - ▼ **Product Catalogue for Static Control Products for EPAs**
    - **3M™ Static Control Products for EPAs (Electrostatic Protected Area)**