



PRODUCT DATASHEET

# **Extech 400 Series MultiMeters**

# Rugged design with built-in IR Thermometer

Extech 400 Series Multimeters are available with or without the built-in InfraRed thermometer, select auto or manual ranging, True RMS or averaging, and choose the meter you want at a price you can afford.



## **Common Features:**

- Large backlit LCD display with easy-to-read 1" digits
- Type K thermometer built-in for temperature measurements
- Low current capability: measure down to 0.1µA
- Input fuse protection and mis-connection warnings
- Complete with CAT III test leads, multi-position tilt stand and velcro strap for hanging, protective holster with test lead holder, bead wire temperature probe (-4 to 482°F/-20 to 250°C), and 9V battery

### Model EX410/EX411

- True RMS (EX411)
- Manual Ranging

#### Model EX420/EX430

- True RMS (EX430)
- Autoranging
- Capacitance
- Frequency

#### **Model EX450**

- Built-in IR Thermometer
- Autoranging

#### **Model EX470**

- Built-in IR Thermometer
- True RMS
- Autoranging
- Capacitance
- Frequency
- Relative function



**Built-In IR Thermometer** EX450 and EX470 models offer built-in InfraRed Thermometer



ω  ω ω			BSSSI CO	Social Control	5.18	518
Specifications	EX410	EX411	EX420	EX430	EX450	EX470
Temperature (IR)	_	_	_	_	√ -58 to 518°F	√ -58 to 518°F
					(-50 to 270°C)	(-50 to 270°C)
Averaging/True RMS	Averaging	✓ True RMS	Averaging	✓ True RMS	Averaging	✓ True RMS
Basic Accuracy (VDC)	±0.5%	±0.3%	±0.3%	±0.3%	±0.5%	±0.3%
AC Voltage	1mV to 750V	1mV to 750V	0.1mV to 750V	0.1mV to 750V	1mV to 750V	0.1mV to 750V
DC Voltage	0.1mV to 1000V					
AC Current	0.1mA to 20A	0.1mA to 20A	0.1µA to 20A	0.1µA to 20A	0.1μA to 20A	0.1µA to 20A
DC Current	0.1µA to 20A	0.1μA to 20A	0.1µA to 20A	0.1μA to 20A	0.1μA to 20A	0.1µA to 20A
Resistance	$0.1\Omega$ to $20M\Omega$	$0.1\Omega$ to $20M\Omega$	$0.1\Omega$ to $40M\Omega$	$0.1\Omega$ to $40M\Omega$	$0.1\Omega$ to $20M\Omega$	$0.1\Omega$ to $40M\Omega$
Capacitance	_	_	✓ 0.01nF to 100µF	✓ 0.01nF to 100µF	_	✓ 0.01nF to 100µF
Frequency	_	_	✓ 0.001Hz to 10MHz	✓ 0.001Hz to 10MHz	_	✓ 0.001Hz to 10MHz
Temperature (Type K)	-4 to 1382°F	-4 to 1382°F	-4 to 1382°F	-4 to 1382°F	_	-4 to 1382°F
	(-20 to 750°C)	(-20 to 750°C)	(-20 to 750°C)	(-20 to 750°C)		(-20 to 750°C)
Duty Cycle	_	_	✓ 0.1% to 99.9%	✓ 0.1% to 99.9%	_	0.1% to 99.9%
Continuity / Diode	Yes	Yes	Yes	Yes	Yes	Yes
Dimensions	7.4x3.2x2"(187x81x50mm)	7.4x3.2x2"(187x81x50mm)	7.4x3.2x2"(187x81x50mm)	7.4x3.2x2"(187x81x50mm)	7.4x3.2x2"(187x81x50mm)	7.4x3.2x2"(187x81x50mm)
Weight	0.75lbs (342g)					
Warranty	1 year	1 year	1 year	√ 3 years	✓ 3 years	√ 3 years

# **Ordering Information**

EX410Manual Ranging MultiMeter
EX410-NISTEX410 MultiMeter w/ NIST Certificate
EX411True RMS Manual Ranging MultiMeter
EX411-NISTEX411 MultiMeter w/ NIST Certificate
EX420Autoranging MultiMeter
EX420-NISTEX420 MultiMeter w/ NIST Certificate
EX430True RMS Autoranging MultiMeter
EX430-NISTEX430 MultiMeter w/ NIST Certificate
EX450Autoranging MultiMeter + IR Thermometer
EX450-NISTLEX450 MultiMeter w/ NIST Certificate
<b>EX470</b> True RMS Autoranging MultiMeter + IR Thermometer
EX470-NISTLEX470 MultiMeter w/ NIST Certificate

## **Accessories**

CA500	Case with shoulder strap and side pockets
1P8/3	Replacement Bead wire Temperature Probe
HC500	Magnetic Hanging Strap
114300	wagneuc nanging onap







